

VTM119+Surface Mounted Box



Installation



Step1 Drill holes in the wall according to holes on the surface mount box, and then put expansion tube in the holes.

Step2 Fix the surface mount box on the wall with ST4×25 screws.

Step3 Install M3×6 screws on the top of the surface mount box to prevent water leakage.

Step4 Thread the cable through the bracket, and then connect the cables to cables on the wall.

Step5 Fix the bracket on the surface mount box with M3×6 screws.

Step6 Fix the outdoor station (VTO) on the bracket with M3×16 screws.

Step7 Apply sealant to gaps between the surface mount box and the wall.

Material: AL5052Dimensions: 150.2mm×411.3mm×127.0mm (5.91"×6.19"×5.00")

Dimensions (mm[inch])





Rev 001.001 © 2019 Dahua. All rights reserved. Design and specifications are subject to change without notice. Pictures in the document are for reference only, and the actual product shall prevail.